

CMS MARK® CMS 3255T

This is to certify that the Factory Production Control System of:

Regency Glass Limited
Unit 2 Bridgewater Business Park
West Bridgewater Street
Leigh
Lancashire
WN7 4HB

has been approved and granted the CENSolutions CMS Mark in respect of their compliance to:

Glass in Building – Thermally Toughened Soda Lime Silicate Safety Glass
BS EN 12150-2:2004
Evaluation of Conformity/Product Standard

For and on behalf of CENSolutions Ltd

Joint Managing Director

Licence granted: 1 September 2017

Re-issued: 25 August 2020



This certificate remains the property of CENSolutions Ltd and may be withdrawn at any time following failure to achieve the appropriate standard required by the CENSolutions Ltd auditing system.

Current status of Licensees can be determined by written application to CENSolutions Ltd.



CENSolutions Ltd
Barn 8 Office 7B
Dunston Business Village
Dunston
Stafford
ST18 9AB

tel: +44 (0)1785 716625 email: info@censolutions.com www.censolutions.com

company reg.no: 4931820

Page 1 of 3

CMS 3255T

Regency Glass Limited
Unit 2 Bridgewater Business Park
West Bridgewater Street
Leigh
Lancashire
WN7 4HB



CMS MARK®

Glass in Building – Thermally Toughened Soda Lime Silicate Safety Glass
BS EN 12150-2:2004

Evaluation of Conformity/Product Standard

Clear/tinted toughened glass meeting Impact Class 1 (BS EN 12600)

Thickness (mm)	Tolerance (mm)
4.0	± 0.2
6.0	± 0.2
8.0	± 0.3
10.0	± 0.3

Clear low iron toughened glass meeting Impact Class 1 (BS EN 12600)

Thickness (mm)	Tolerance (mm)
4.0	± 0.2
6.0	± 0.2

Coated toughened glass meeting Impact Class 1 (BS EN 12600)

Coating	Thickness (mm)	Tolerance (mm)
Pilkington K	4.0 + 6.0	± 0.2
Planibel G	4.0 + 6.0	± 0.2
Activ	4.0	± 0.2
Active	6.0	± 0.2
Solgard	4.0	± 0.2
Climaguard NT	4.0	± 0.2
Climaguar NT	6.0	± 0.2
Planitherm Total	4.0 + 6.0 + 10.0	± 0.2
Bioclean	4.0 + 6.0	± 0.2

Licence first granted: 1 September 2017

Re-issued: 25 August 2020



This certificate remains the property of CENSolutions Ltd and may be withdrawn at any time following failure to achieve the appropriate standard required by the CENSolutions Ltd auditing system.

Current status of Licensees can be determined by written application to CENSolutions Ltd.



CENSolutions Ltd
Barn 8 Office 7B
Dunston Business Village
Dunston
Stafford
ST18 9AB

tel: +44 (0)1785 716625 email: info@censolutions.com

www.censolutions.com

company reg.no: 4931820

Page 2 of 3

CMS 3255T

Regency Glass Limited Unit 2 Bridgewater Business Park West Bridgewater Street Leigh Lancashire WN7 4HB



Sycamore Tafetta Warwick

CMS MARK®

Glass in Building - Thermally Toughened Soda Lime Silicate Safety Glass BS EN 12150-2:2004

Evaluation of Conformity/Product Standard

Pilkington patterned toughened glass meeting Impact Class 1 (BS EN 12600) in 4 mm and 6 mm thickness

Artic	Delta	Minster
Autumn	Digital	Oak
Chantilly	Everglade	Orchid
Charcoal Sticks	Flemish	Pelerine
Contour	Florielle	Satin
Cotswold	Mayflower	Stippolyte

Guardian patterned toughened glass meeting Impact Class 1 (BS EN 12600) in 4 mm thickness

Brisa

Flemish

Satin Deco (4mm and 6mm thickness)

Cascade

Leaf

Regency patterned toughened glass meeting Impact Class 1 (BS EN 12600) in 4 mm thickness

Bark

Satin Deco (4mm and 6mm thickness) Westminster

Leaf

Stipple

Other patterned toughened glass meeting Impact Class 1 (BS EN 12600) in 4 mm thickness

Glue Chip

Licence first granted 1 September 2017

Re-issued: 25 August 2020



This certificate remains the property of CENSolutions Ltd and may be withdrawn at any time following failure to achieve the appropriate standard required by the CENSolutions Ltd auditing system.

Current status of Licensees can be determined by written application to CENSolutions Ltd.

CENSOLUTIONS°

CENSolutions Ltd Barn 8 Office 7B Dunston Business Village Dunston Stafford ST18 9AB

tel: +44 (0)1785 716625 email: info@censolutions.com

www.censolutions.com

company reg.no: 4931820 Page 3 of 3